

Rendelési segédlet

PD111		-	X	-	X	X	X	X	-	X	-	X
Méréstartomány, bar												
0...-1	*V			1	P	0	B					
0...0.16	*G			1	6	0	M					
0...0.25	G			2	5	0	M					
0...0.4	G			4	0	0	M					
0...0.6	G			6	0	0	M					
0...1	G			1	P	0	B					
0...1.6	G			1	P	6	B					
0...2.5	G			2	P	5	B					
0...4	G			4	P	0	B					
0...6	G			6	P	0	B					
0...10	G			0	1	0	B					
0...16	G			0	1	6	B					
0...25	G			0	2	5	B					
-0.2...0.2**	C			2	0	0	M					
-0.3...0.3**	C			3	0	0	M					
-0.5...0.5**	C			5	0	0	M					
-0.8...0.8**	C			8	0	0	M					
-1...1**	C			1	P	0	B					
-1...3**	C			3	P	0	B					
-1...5	C			5	P	0	B					
-1...9**	C			9	P	0	B					
-1...15**	C			0	1	5	B					
-1...24**	C			0	2	4	B					
Pontosság												
0.5 %												5
0.25 %												2
Gépészeti csatlakozás												
G1/2"												7
G1/4"												8

Megjegyzés *V – vákuum, *G – relatív, *C – kombinált

** Csak 0.5 % pontossággal és G1/2" csatlakozással rendelhető

